

REQUEST FOR QUOTATION

REFERENCE NO.: MR21-08-089

We are inviting all interested contractors/suppliers to submit their best quotation for the **PROCUREMENT FOR THE SUPPLY OF LABOR AND MATERIALS FOR THE REPAIR OF FIRE DETECTION AND ALARM SYSTEM (FDAS) AND FIRE PROTECTION SYSTEM (FPS) OF THE NDC BUILDING.**

Requirements:

SPECIFICATION	QTY	UNIT	ESTMATED UNIT COST	ESTIMATED TOTAL COST
A. Repair /rehabilitation and reconditioning of Automatic Fire Sprinkler System (AFSS) and Fire alarm and detection system (FDAS) of the NDC Building which includes. Replacement and repair of various floor control valve assembly (FCV), Auxiliary drain valve, fire pump's back / return pipe, fire alarm gong pipes, fire alarm bells, manual pull, smoke and heat detectors.				
Basement Level:				
Replacement of 4 " dia. B.I pipe for Fire pump's return / back to tank including Brackets, hangers & supports & Painting works	5	m	7,081.00	35,405.00
Replacement of pipe at fire alarm gong.	1	lot	22,600.00	22,600.00
Replacement of damage Floor Control Valve @ Basement Level	1	pc/s	19,150.00	19,150.00
Replacement of Fire Alarm Bell @ Basement level	1	pc/s	5,525.00	5,525.00
Ground Floor:				
Replacement of Alarm bell	1	pc/s	5,525.00	5,525.00
Replacement of Manual Pull station	1	pc/s	5,156.00	5,156.00
2nd Floor:				
Replacement of Fire Alarm Bell	1	pc/s	5,525.00	5,525.00
Replacement of Manual Pull station	1	pc/s	5,156.00	5,156.00
3rd Floor:				
Repair of Auxiliary Drain Valve	1	lot	3,150.00	3,150.00
Replacement of Floor Control Valve	1	pc/s	19,150.00	19,150.00
5th Floor:				
Repair of Floor Control Valve	1	lot	19,150.00	19,150.00

Replacement of Tamper Switch	1	pc/s	6,148.00	6,148.00
6th Floor:				
Replacement of Smoke Detector	1	pc/s	3,606.00	3,606.00
Replacement of Floor Control Valve	1	pc/s	19,150.00	19,150.00
Provision of Cover for Water Floor switch	1	pc/s	1,138.00	1,138.00
8th Floor:				
Replacement of Floor Control Valve	1	pc/s	19,980.00	19,980.00
10th Floor:				
Replacement of Floor Control Valve	1	pc/s	19,150.00	19,150.00
Replacement of defective manual Pull Station	1	pc/s	5,156.00	5,156.00
11th Floor:				
Rectification of Incorrect zone termination of Heat and Smoke Detector @11th floor	1	lot	13,125.00	13,125.00
Replacement of defective smoke detector	1	pc/s	3,606.00	3,606.00
Penthouse:				
Replacement of defective smoke detector	2	pc/s	3,606.00	7,212.00
Replacement of defective Alarm Bell	1	pc/s	5,525.00	5,525.00
Replacement of defective Manual Pull station	1	pc/s	5,156.00	5,156.00
B. Complete flushing, Draining and Cleaning of the entire Automatic Fire sprinkler system including Risers, Feed Main, Crossmain & Branchlines in all floors and levels and fire Storage Tank of the NDC building.	1	lot	45,000.00	45,000.00
C. Testing and Commissioning including Fire Sprinkler Testing	1	lot	19,698.86	19,698.86

